Region 3 GPRA Baseline RCRA Corrective Action Facility

Lehighton Electronics

Route 443 - Road # 1 Lehighton, PA 18235 Congressional District 11 EPA ID #: PAD002399186 Last Updated 12/17/2003

Current Progress at the Site

The following Corrective Action work has been completed at the facility:

- RCRA Facility Investigation to provide information on the nature and extent of environmental contamination at the site;
- Corrective Measure Study to evaluate final clean-up measures needed; and
- Operation of an interim pump and treat system to clean-up contaminated
- Installation of a treatment system for groundwater clean-up and a water supply to the building

EPA issued a Final Decision and Response to Comments to Lehighton on April 8, 2002. The Final Decision requires continued remediation and monitoring the contaminated groundwater, removal a former TCE storage tank and a fuel oil tank, and the installation of a potable water supply that meets EPA drinking water standards. A RCRA Consent Order to complete the remediation was issued in June 2003. The facility is working on final plans to complete the required corrective action work.

Site Description

The Lehighton facility has manufactured printed circuit boards at this location since 1965. It is located about four miles southwest of Lehighton on a one-half acre lot in a sparsely populated area. Materials handled at the site includes various metals and organic compounds. Trichloroethylene (TCE) was used as a solvent prior to 1980. 1-1-1-Trichloroethane has been used since 1980. Groundwater at the facility contains TCE at levels above drinking water standards.

Site Responsibility

RCRA Corrective Action activities at this facility are being conducted under the supervision of EPA Region 3 with assistance from the State.

Contaminants

The groundwater contamination at the facility is now at approximately 30 parts per billion of TCE. The interim pump and treat system has reducing the levels of contamination in the groundwater. A few soil

samples contained polynuclear aromatic hydrocarbon compounds above EPA's health-based screening levels, but below State action levels. The soil contamination is not related to manufacturing or waste handling activities. Off-site properties are not impacted by facility contamination. Annual monitoring of surrounding residential wells shows no TCE or breakdown products in the well water.

Community Interaction

The nearest resident is contacted annually by Lehighton for well monitoring.

Government Contacts

EPA Project Manager Ms. Maureen Essenthier - 3WC22 U.S. Environmental Protection Agency - Region III 1650 Arch Street Philadelphia, PA 19103-2029 Phone: (215) 814-3416

Email: essenthier.maureen@epa.gov

Bharat Bham Hydrogeologist Pennsylvania Department of Environmental Protection Bethlehem District Office Phone: (610) 861-2070

For more information about EPA's corrective action webpage, including Environmental Indicators, please visit our site at: www.epa.gov/reg3wcmd/correctiveaction.htm

Facility Contact

Mr. Glen Caputo Environmental Manager Lehighton Electronics, Inc. P.O. Box 328 Lehighton, PA 18235-0328 Phone: (610) 377-5990